

All-In-One Solutions





Are you a:

Contractor? Technician? First Responder?

We made a Go-Kit just for you!





Everything you need ... in a Go-Kit!

At PRO, we've taken our experience from working in the field and transformed it into a comprehensive solution for all your fiber optic gear. Many industries, many tools to track, many problems... One solution - Go-Kit.®

Whether you are an installer, technician or emergency responder, there's nothing more convenient than having all your equipment ready to go when a job springs up - we know this from experience. With the PRO Go-Kit you will have everything you need to clean, test, inspect and connect fiber communications conveniently stored so you can "grab and go".

Every Go-Kit is purpose-built. We have assembled the kits to accommodate a wide variety of situations that technicians are likely to encounter on the job. When it comes to saving time and doing the job right, there's only one answer, Work with a PRO!

Servicing a variety of fiber optic industries...











There's a Go-Kit® to suit every task and every budget!

If you like what you see here, check out all the individual Go-Kit configurations at our website. Visit precisionratedoptics.com/product-category/kits/ and request a quote!





Go-Kit Backpacks

This is no ordinary backpack. Go-Kit Backpacks are the ultimate solution for fiber technicians everywhere. Go-Kit Backpacks come in industry-configured designs and can include a fusion splicer, OTDR, PM/LS, VFL, cleaning supplies and tools all in one convenient, rugged and field-tested backpack. Can't find what you need? Ask us about customizing your own Go-Kit Backpack at no additional cost!



Go-Kit Optical Loss Test Kits

Whether you are a fiber technician or contractor, Optical Loss Go-Kits contain all the tools necessary to quickly measure loss, power levels, inspect and clean connector end-faces. Features including both SM, MM testing capabilities, test cables and SC, ST, FC and universal adapters in a semi-rigid carrying case make PRO the best fiber test kit on the market.



Go-Kit Tool Kits

Precision Rated Optics has configured a variety of Go-Kit tool kits based on different field operations. Whether you simply need hand tools for your inventory or field termination tools, PRO has you covered. No where else in the industry will you find one product line that has everything you need - PRO Go-Kits.



Go-Kit Cleaning Kits

Certain cleaning supplies are needed on *any* fiber job. We've chosen the most commonly-used items and configured several Go-Kit Cleaning Kits. Get just the basics or upgrade for more! Inspect, Clean, Evaluate ... Test (ICE-T). Always inspect your endface to determine its quality to choose the preferred cleaning method.





Everything you need ... in a Go-Kit®

Everything you need, in a Go-Kit! PRO offers a variety of Go-Kit styles including, Go-Kit Backpacks, Go-Kit Optical Loss Test Kits, Go-Kit Cleaning Kits, and Go-Kit Tool Kits. If we don't have exactly what you need, contact us at sales@precisionratedoptics.com for your custom Go-Kit. Many industries, many tools to track, many problems ... One solution - Go-Kit!

Our Go-Kit Backpack is no ordinary backpack. PRO Go-Kit Backpacks are water resistant, lightweight and practical, and can safely store and transport all of your test equipment, hand tools and cleaning supplies. There's even a special soft-shelled compartment to accommodate up to a 17" laptop! Each Go-Kit has been configured to contain the necessary equipment based on which industry you are in.

If you don't see what you need, give us a call and let the experts at PRO design a custom Go-Kit that best fits your exact needs.



Technician Go-Kit®

The Technician Go-Kit is the perfect solution for technicians that install, test, troubleshoot and restore fiber networks. Performing an OTDR test on a live fiber can damage active equipment. This kit contains a fiber identifier that will allow you to know if the fiber is live before you perform any tests. The power meter, light source and VFL are essential for basic continuity and power level checks. Also, included in select configurations is an inspection scope to ensure end face connectors are clean and not damaged. For new installations the OTDR will graph any potential issues along that fiber span. Depending on configuration, a core-alignment fusion splicer or ribbon fusion splicer is included to allow new fiber connections or to repair fiber breaks.

GOK-CON-K1 (CORE ALIGNMENT/SM OTDR)

dok con ki (coke Alignment) sin otok,				
OFS-960S	Core Alignment Fusion Splicer (Not SOC Compatible)			
OFT-1000	Smart OTDR (1310/1550nm, 24dB/22dB)			
LS-500D	Singlemode Light Source (1310/1550nm)			
PM-200B	Optical Power Meter w/built-in VFL (50dBm ~ + 26dBm)			
OFI-30	Optical Fiber Identifier (-50~+0dBm)			
VFL-5	PRO Mini Visual Fault Locator 1mw			
PS-S-1KM-CUCU-1	Launch Box SM9 1KM SC/UPC-SC/UPC			
GOK-ACC-OSP	Go-Kit Outside Plant Accessories			
GOK-ERBKPKLTOP	Go-Kit Roller Backpack			



GOK-CON-K1
Technician Go-Kit 1

GOK-CON-K2

(CORE ALIGNMENT/QUAD OTDR/PM DATA STORAGE)

OFS-935C	Core Alignment Fusion Splicer (SOC Compatible)
OFT-2000	Quad OTDR (850/1300/1310/1550nm, 20/26/30/32dB)
LS-201Q	Quad Light Source (850/1300/1310/1550nm)
PM-204B	Optical Power Meter w/data storage (50dBm ~ + 26dBm)
OFI-30	OFI-30 Fiber Identifier -50~+0dBm
VFL-5	PRO Mini Visual Fault Locator 1mw
VIP-45-K1	Video Inspection Probe Kit 1
PS-S-1KM-CUCU-1	Launch Box SM9 1KM SC/UPC-SC/UPC
PS-M-300-CUCU-1	Launch Box M62 300M SC/UPC-SC/UPC
GOK-ACC-OSP	Go-Kit Outside Plant Accessories
GOK-ERBKPKLTOP	Go-Kit Roller Backpack



GOK-CON-K1
Technician Go-Kit 2

GOK-CON-K3 (RIBBON SPLICER/QUAD OTDR)

OFS-936R	Ribbon Fusion Splicer
OFT-2000	Quad OTDR (850/1300/1310/1550nm, 20/26/30/32dB)
LS-201Q	Quad Light Source (850/1300/1310/1550nm)
PM-204B	Optical Power Meter w/data storage (50dBm ~ + 26dBm)
OFI-30	OFI-30 Fiber Identifier -50~+0dBm
VFL-5	PRO Mini Visual Fault Locator 1mw
VIP-45-K1	Video Inspection Probe Kit 1
PS-S-1KM-CUCU-1	Launch Box SM9 1KM SC/UPC-SC/UPC
PS-M-300-CUCU-1	Launch Box M62 300M SC/UPC-SC/UPC
GOK-ACC-OSP	Go-Kit Outside Plant Accessories
GOK-ERBKPKLTOP	Go-Kit Roller Backpack



GOK-CON-K3
Technician Go-Kit 3



Emergency Response Go-Kit®

When networks are down it costs companies tens of thousands of dollars. Getting networks back online as quickly as possible requires a highly trained technician with the proper equipment and tools. The Emergency Response Go-Kit is designed to include everything a technician needs to quickly identify the problem area (OTDR, Power Meter/Light source, VFL and Optical Fiber Identifier) and then repair the break and get connections restored as quickly as possible. Included in the Emergency Restoration Go-Kit is a variety of supplies to support field terminations and connectorization.

GOK-ERK-K1

OFS-935C	Core Alignment Fusion Splicer (SOC Compatible)				
OFT-2000	Quad OTDR (850/1300/1310/1550nm, 20/26/30/32dB)				
LS-201Q	Quad Light Source (850/1300/1310/1550nm)				
PM-204B	Optical Power Meter w/data storage (50dBm ~ + 26dBm)				
OFI-30	OFI-30 Fiber Identifier -50~+0dBm				
VFL-5	PRO Mini Visual Fault Locator 1mw				
VIP-35-DATA	3.5" VIP kit w/ Data Storage				
PS-S-1KM-CUCU-1	Launch Box SM9 1KM SC/UPC-SC/UPC				
PS-M-300-CUCU-1	Launch Box M62 300M SC/UPC-SC/UPC				
GOK-ACC-STD	Go-Kit Standard Accessories				
GOK-ERBKPKLTOP	Go-Kit Roller Backpack				



GOK-ERK-K1
Emergency Response Go-Kit

Fiber-to-the-Home Go-Kit®

Both economical and fully-featured, this Go-Kit includes all of the standard basic FTTX installation equipment: an Optical Fiber Identifier to check for live fiber before splicing into the network with the supplied Core Alignment fusion splicer, and an Optical Power Meter and VFL to verify signal continuity and power upon completing installation.

GOK-FTTx-K1

OFS-960S	Core Alignment Fusion Splicer (Not SOC Compatible)
PM-200B	Optical Power Meter w/built-in VFL (50dBm ~ + 26dBm)
OFI-30	Optical Fiber Identifier (-50~+0dBm)
VFL-5	PRO Mini Visual Fault Locator 1mw
GOK-ACC-STD	Go-Kit Standard Accessories
GOK-ERBKPKLTOP	Go-Kit Roller Backpack






Accessory Kits



GOK-ACC-OSP
Outside Plant Accessories Go-Kit

KIT INCLUDES:





GOK-ACC-STD
Standard Accessories Go-Kit

KIT INCLUDES:

PRO-BAG-LARGE	12" x 10" x 11" Black Canvas Bag Large
PC-S-ACUCU01F	SC/UPC-SC/UPC PatchCord Simplex Single Mode 9/125 3mm OD 1 Meter
PC-S-ACACU01F	SC/APC-SC/UPC PC Simplex SM9 3mm 1M
PC-S-AFUCU01F	FC/UPC-SC/UPC PC Simplex SM9 3mm 1M
PC-S-CLUCU01F	LC/UPC-SC/UPC PC Simplex SM9 2mm 1M
CA-S-LC-S6DPZ	Mating Sleeve LC/UPC SM Duplex (Z)
CA-S-SC-S6SPZ	Mating Sleeve SC/UPC SM Simplex (Z)
CA-S-SC-A6SPZ	Mating Sleeve SC/APC SM, Flanged Simplex
PRO-LFW-100	Lint-free Wipe 3" x 3" (100CT)
PRO-CC-AQ	PRO-CC-AQ Connector Cleaner Water Base
CS-250	PRO Quick Click - 2.5mm SC,FC,ST
CS-125	PRO Quick Click - 1.25mm (LC)
CST-1900	Round Cable Stripper
JIC-186	Kevlar Shears
PRO-CT-001	Fiber Optic Cleaning Cassette
PRO-FSC-200	Fiber Scrap Container
PRO-0008	Electrical Tape
10-099H	Utility Knife
SR-101	Seam Ripper
SMART-STRIP	Buffer Tube Stripper
KN-7	Cable Splicing Knife
PRO-AA-SA	PRO Stainless Steel Pointed Tweezer
PRO-STRIP-3HOLE	Fiber Optic Three Hole Stripper
RMC-6	Measurement Scale 6"
PRO-0017	Fiber Buffer Tube Stripper
SHARPIE-BK	Black Sharpie
63816	6" Diagonal Cutters
RCT-PLYERS	Needle Nose Plyers - 8"



Optical Loss Test Kits



Everything you need to CLEAN, INSPECT & TEST!

Precision Rated Optics has developed Optical Loss Go-Kits designed for specific markets within the communications industry. With new advanced capabilities that make testing simple, PRO Optical Loss Go-Kits are the best "go-to" kits for anyone involved in first-line optical fiber cabling installation and verification.

Whether you are a fiber technician or contractor, our expertly configured kits contain all the tools necessary to quickly measure loss, power levels, inspect and clean connector end-faces. Features including both SM and MM testing capabilities along with Test Cables and SC, ST, FC and universal adapters in a semi-rigid carrying case make PRO the best fiber test kit on the market.

FEATURES:

- Semi-Rigid Carrying Case
- Power Meter (Six Wavelength)
- · Light Source
- 400x Fiber Inspection Scope
- Cleaning Supplies



GOK-OLS-K1

Optical Loss Test Go-Kit 1 (SM)

KIT INCLUDES:

LS-102D	Light Source (1310/1550nm) fixed			
PM-102B	Power Meter (-40~+23)			
VFL-5	PRO Mini Visual Fault Locator 1mW			
HM-C400S	Fiber Optic Inspection Scope (400x)			
PC-S-ACUCU01F	SM9 3mm Simplex SM UPC Patchcord 1M			
PC-S-CLUCU01F	2mm Simplex SM UPC Patchcord 1M			
CA-S-SC-S6SPZ	Mating Sleeve SC/UPC SM Simplex			
CA-S-LC-S6DPZ	Mating Sleeve LC/UPC SM Duplex			
PRO-LFW-100	PRO-LFW-100 Lint-free Wipe (100ct.)			
PRO-CC-AQ	PRO-CC-AQ Connector Cleaner Water Base			
SRC-1-GOK-LOGO	Semi-rigid case 100 Series			



GOK-OLS-K2

Optical Loss Test Go-Kit 2 (SM w/Data Log)

KIT INCLUDES:

LS-102D	Light Source (1310/1550nm) fixed
PM-204B	Power Meter (-50~+26 w/Data Storage)
VFL-5	PRO Mini Visual Fault Locator 1mW
HM-C400S	Fiber Optic Inspection Scope (400x)
PC-S-ACUCU01F	SM9 3mm Simplex SM UPC Patchcord 1M
PC-S-CLUCU01F	2mm Simplex SM UPC Patchcord 1M
CA-S-SC-S6SPZ	Mating Sleeve SC/UPC SM Simplex
CA-S-LC-S6DPZ	Mating Sleeve LC/UPC SM Duplex
PRO-LFW-100	PRO-LFW-100 Lint-free Wipe (100ct.)
PRO-CC-AQ	PRO-CC-AQ Connector Cleaner Water Base
SRC-2-GOK-LOGO	Semi-rigid case 200 Series



GOK-OLS-K3

Optical Loss Test Go-Kit 3 (SM&MM)

KIT INCLUDES:

LS-201Q	Light Source (850/1300/1310/1550nm)
PM-102B	Power Meter (-40~+23)
VFL-5	PRO Mini Visual Fault Locator 1mW
HM-C400S	Fiber Optic Inspection Scope (400x)
PC-S-ACUCU01F	SM9 3mm Simplex SM UPC Patchcord 1M
PC-S-CLUCU01F	2mm Simplex SM UPC Patchcord 1M
CA-S-SC-S6SPZ	Mating Sleeve SC/UPC SM Simplex
CA-S-LC-S6DPZ	Mating Sleeve LC/UPC SM Duplex
PC-M-ACUCU01F	SC/UPC-SC/UPC PC Simplex M62 3mm 1M
PC-M-CLUCU01F	LC/UPC-SC/UPC PC Simplex MM62 2mm 1M
CA-S-SC-M6SPB	Mating Sleeve SC/UPC MM Simplex (PB)
CA-S-LC-M6DPB	Mating Sleeve LC/UPC MM Duplex (PB)
PRO-LFW-100	PRO-LFW-100 Lint-free Wipe (100ct.)
PRO-CC-AQ	PRO-CC-AQ Connector Cleaner Water Base
SRC-2-GOK-LOGO	Semi-rigid case 200 Series



GOK-OLS-K4

Optical Loss Test Go-Kit 4 (SM&MM w/Data Log)

KIT INCLUDES:

LS-201Q	Light Source (1310/1550nm) fixed
PM-204B	Power Meter (-40~+23)
VFL-5	PRO Mini Visual Fault Locator 1mW
HM-C400S	Fiber Optic Inspection Scope (400x)
PC-S-ACUCU01F	SM9 3mm Simplex SM UPC Patchcord 1M
PC-S-CLUCU01F	2mm Simplex SM UPC Patchcord 1M
CA-S-SC-S6SPZ	Mating Sleeve SC/UPC SM Simplex
CA-S-LC-S6DPZ	Mating Sleeve LC/UPC SM Duplex
PC-M-ACUCU01F	SC/UPC-SC/UPC PC Simplex M62 3mm 1M
PC-M-CLUCU01F	LC/UPC-SC/UPC PC Simplex MM62 2mm 1M
CA-S-SC-M6SPB	Mating Sleeve SC/UPC MM Simplex (PB)
CA-S-LC-M6DPB	Mating Sleeve LC/UPC MM Duplex (PB)
PRO-LFW-100	PRO-LFW-100 Lint-free Wipe (100ct.)
PRO-CC-AQ	PRO-CC-AQ Connector Cleaner Water Base
SRC-2-GOK-LOGO	Semi-rigid case 200 Series



Tool Kits







PRO-TK-PROFProfessional Termination Go-Kit



PRO-TK-DELUXEDeluxe Termination Go-Kit

Item / Model No.	Description	PRO-TK- STARTER	PRO-TK- PROF	PRO-TK- DELUXE
PRO-BAG-LARGE	12" x 10" x 11" Black Canvas Bag Large	Х	X	X
HM-C400S	Fiber Optic Inspection Scope (400X)	X	X	X
PRO-FSC-200	PRO-FSC-200 Fiber Scrap Container	X	X	X
SHARPIE-BK	Black Sharpie	X	X	X
501473-31R25	Empty syringe w/ .9mm Needle (25pk)	X	X	X
PRO-CP410-1	Optic Prep Tissue - 1 Packet	X	X	X
PRO-CW34	Fiber Optic Cleaning Wipes	X	X	X
PRO-IA-4OZ	Empty 4oz bottle for Alcohol	X	X	X
RMC-6	Measurement Scale 6" (150mm)	X	X	X
WO-1067G	Safety Glasses	X	X	X
7090	Loctite Formula 7090 Epoxy Hardener	X	X	X
PP-575	Hand polish pad (5.75") 1/16" thick	X	X	X
UC-8039	Fiber Optic Crimp Tool with Die	X	X	X
CS-30-DE	Double Ended Carbide Scribe	X	X	X
FOPD-25	Universal Fiber Optic Polishing Disk	X	X	X
680	Anaerobic Adhesive Hardener	X	X	X
JIC-186	Kevlar Shears	X	X	X
JIC-375	Fiber Optic Stripper Three Hole	X	X	X
PRO-9111A	Glass Polish Plate 6" x 9"	X	X	X
PRO-0008	Electrical Tape	X	X	X
PRO-0109-5-1-03	Polish Film 3 in 1 (5, 1, .3um) 25pk	X		X
FOPD-LC	Aluminum Fiber Optic Polishing Disk LC			X
SMART-STRIP	Buffer Tube Stripper		X	
PRO-0102-1	1 um Alum. Oxide Polish Film 9"x 6.5"		X	
PRO-0102-03	.3um AL Oxide Polish Film 0.3um 9"x6.5"		X	
PRO-0102-5	5 um Silicon Carbide Polish Film 9"x6.5"		X	
PRO-1008	Canned Air - Tech Spray 10oz		X	











PRO-TK-QWIKTERM

Quick Termination Go-Kit

PRO-TK-VGROOVE

V-Groove Cleaning Go-Kit

PRO-TK-HANDTOOL

PRO-TK-OSP

Handtool Cable Prep Go-Kit Outside Plant Handtool Go-Kit

Item / Model No.	Description	PRO-TK- QWIKTERM	PRO-TK- VGROOVE	PRO-TK- HANDTOOL	PRO-TK- OSP
PRO-BAG-LARGE	12" x 10" x 11" Black Canvas Bag Large	X			Х
PRO-BAG-SM-GOKL	12" x 10" Black Canvas Bag Small		X	X	
JIC-186	Kevlar Shears	X		X	X
JIC-375	Fiber Optic Stripper Three Hole	X		X	
HM-C400S	Fiber Optic Inspection Scope (400X)	X			
PRO-FSC-200	PRO-FSC-200 Fiber Scrap Container	X			
SHARPIE-BK	Black Sharpie	X			X
FS100	Polishing/Work mat (Black) (22 x 14)	X			
PRO-6000N	Fiber Optic Cleaver	X			
PRO-CC-QC	PRO-CC-QC Connector Cleaner- Pump-Spray	X	X		
PRO-LFW-100	PRO-LFW-100 Lint-free Wipe (100ct.)	X	X		
FB-11VG	V-Groove Cleaning Swabs (50/tube)		X		
VGB-003-CR	V-Groove Brush		X		
FOM-0005	Swabs Mini Foam 2.5mm 50 Pack		X		
D5111	Electrode Sharpener/Cleaning Pack		X		
CSR-1575	Cable Slitting and Ring Tool			X	
PRO-CP410-1	Optic Prep Tissue - 1 Packet			X	
JIC-842	Telecom Long Nose Pliers			X	
JIC-63050	High Leverage Cable Cutters			X	X
CST-1900	Round Cable Strippers			X	X
KN-7	Cable Splicing Knife			X	Χ
10-099Н	Utility Knife			X	X
FOD-2000	Fiber Optic Drop Cable Slitter			X	Χ
PRO-0008	Electrical Tape (1)				X
SR-101	Seam Ripper (1)				X
SMART-STRIP	Buffer Tube Stripper (1)				X
PRO-AA-SA	Stainless Tweezers (1)				Х
PRO-STRIP-3HOLE	Fiber Optic Stripper Three Hole (1)				X
RM6	Measurement Scale 6" (150mm) (1)				Х
PRO-0017	Fiber Buffer Tube Stripper (1)				X
63816	6 Inch Diagonal Cutters (1)				Х
RCT-PLYERS	Needle Nose Plyers- 8" (1)				X
ND-631	Hollow Shaft Nut Driver Set (1)				Х
80785	Mid Span Access Tool (1)				X
ACS	Armored Cable Slitter (1)				X





PRO-CK-MPO MPO Cleaning Go-Kit



PRO-CK-MPO-DLX
Deluxe MPO Cleaning Go-Kit

Cleaning Kits

Item Code	Description	PRO-CK- MPO	PRO-CK- MPO-DLX
PRO-BAG-SM-GOKL	10" x 12" Black Canvas Bag	X	
CS-MPO	PRO CS-MPO QuickClick MPO Connector		X
PRO-CT2-022-1	PRO Lens Cleaning Swabs (EA)	X	X
PRO-LFW-100	Lint-free Wipe 3" x 3" (100CT)	X	X
PRO-CC-AQ	PRO-CC-QC Solvent-Based Connector Cleaner - Pump Spray	X	X
CS-125	CS-125 QuickClick 1.25mm (LC)		X
CS-250	CS-250 QuickClick 2.5mm (SC, FC, ST)		X
PRO-CT2-002-015	Cleaning Stick Wrapped 2.5mm 5 (5 Packs)		X
PRO-CT2-002-025	Cleaning Stick Wrapped 1.25mm 5 (5 Packs)		X





Fiber Optic Technician Cleaning Go-Kit



Basic Fiber Optic Cleaning Go-Kit



Fiber Optic Cleaning Go-Kit w/Quick Clicks™



Fiber Optic Cleaning Go-Kit w/Quick Clicks™ and 400x Scope

Cleaning Kits

Item Code	Description	PRO-CK- TECH	PRO-CK-CLEAN- BA	PRO-CK- CLEAN-01	PRO-CK- CLEAN-02
PRO-BAG-SM-NL	X-Large Zipper Bag - 13.5 x 10.5	X			
PRO-BAG-LARGE	12" x 10" x 11" Black Canvas Bag		X	X	X
PRO-CT2-002-015	Cleaning Stick Wrapped 2.5mm (100 Pack)	X	X	X	X
PRO-CT2-002-025	Cleaning Stick Wrapped 1.25mm (100 Pack)	X	X	X	X
TC-1	American Polywater SqueekyKleen Wipes (10)	X	X	X	X
PRO-CC-AQ	PRO Connector Cleaner Water Base	X	X	X	X
PRO-CC-QC	PRO Connector Cleaner- Pump-Spray	X	X	X	X
PRO-LFW-100	Lint-free Wipes (100ct)	X	X	X	X
P1501E-1	Cotton Swab 6" General SM (100 Pack)	X	X	X	X
FOM-0005	Swabs Mini Foam 2.5mm (50 Pack)	X	X	X	X
CP410-1	Optic Prep Pre-saturated Pads (1 Packet)		X	X	X
FOM-CP421-1	Electro-Wash Wipe (MX) (1 Packet)		X	X	X
PRO-CT-001	Fiber Optic Cleaning Cassette		X	X	X
PRO-CT-004	Replacement Cassette Reel		X	X	X
PRO-CS-125	Quick Click™1.25mm (LC)			X	X
PRO-CS-250	Quick Click™2.5mm (SC)			X	X
HM-C400S	400x Fiber Scope				X

